



ENTERED

COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

Type (Circle One): C I N

Received Date: 07/18/18 Received Time: 9:30 Received By: HW Lead: JP
 Incident Date: 7/18/18 Incident Time: 9:00 Assigned to: _____ Assigned Date: _____

CASE NUMBER: **180718 - 01**

COMPLAINANT / REPORTING PARTY:

Name: Margie Valdez RP is from Facility Anonymous
 Organization: Contra Costa County Public Works
 Primary Phone Number: 925-313-7012 Secondary Phone Number: _____
 Email: _____
 Address: _____
 City: _____ State: _____ Zip Code: _____

FACILITY / LOCATION OF INCIDENT:

Name: _____ CUPA Facility I.D.: _____
 Phone Number: _____
 Address: _____ Unit: _____
 City: _____ State: CA Zip Code: _____
 Location Description: On San Pablo Dam Road, 0.6 miles to the south of San Pablo Reservoir entrance

INITIAL INCIDENT DESCRIPTION:

Abandonment of unknown chemical containers on San Pablo Dam Road. No leaking.

INCIDENT TYPE / DESCRIPTION:

Community Warning System Level (Circle Highest Level): N/A 0 1 2 3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion <input type="checkbox"/> Spill or Release <input type="checkbox"/> Startup or Shutdown <input type="checkbox"/> Flaring <input type="checkbox"/> Upset	<input type="checkbox"/> Fatality (one or more) <input type="checkbox"/> > 24 hrs. Hospital, 3 or more people <input type="checkbox"/> Flammable Vapor Cloud > 5,000 lbs.	<input type="checkbox"/> Tank Truck <input type="checkbox"/> Railroad <input type="checkbox"/> On Water <input type="checkbox"/> Pipeline <input type="checkbox"/> Fuel Tank	<input type="checkbox"/> Storm Drain/Creek <input type="checkbox"/> Drug Lab <input checked="" type="checkbox"/> Disposal/Abandonment <input type="checkbox"/> Odor Complaint <input type="checkbox"/> Other:

Time Enroute to Scene: 10:00 Time Arrived On Scene: 10:37 Time Departed From Scene: 11:00

REFERRED TO OTHER AGENCY:



DTSC STATE FUNDING (if applicable): CLU/ERER Number:	STORMWATER STATUS (if applicable): <input type="checkbox"/> Actual Discharge <input checked="" type="checkbox"/> Potential Discharge
--	--

AGENCIES ON SCENE OR NOTIFIED:

<u>Agency Type</u>	<u>Agency</u>	<u>O/N</u>	<u>Contact Person</u>	<u>Phone Number</u>	<u>Case Number</u>
Fire Department					
Law Enforcement					
Air District					
State OES					

REPORT:

9:30, Contra Costa Health Services Hazardous Materials Program (CCHSHMP) received a call from Contra Costa County Public Works about abandonment of unknown chemical containers on San Pablo Dam Road in City of Moraga.
 10:00, HM3 (IW and SH) departed the office.
 10:37, HM3 arrived on scene. No leak from the containers was observed. CCHSHMP visually inspected labels on the chemical containers and the content inside the containers. CCHSHMP presumed one waste antifreeze container and 6 Latex paint containers.
 11:00, CCHSHMP moved the chemical containers on HM3 to County Household Hazardous Waste Facility. HM3 departed the scene.

Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan

Report Prepared by: JP