



CONTRA COSTA
HEALTH SERVICES

COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

Type (Circle One): C I N

Received Date: 02/18/17 Received Time: 10:38 Received By: CT Lead: CT

Incident Date: 2/18/2017 Incident Time: 07:41 Assigned to: CT Assigned Date: 2/18/2017

CASE NUMBER: 17-02-18 - 01

COMPLAINANT / REPORTING PARTY:

Name: CAPTAIN GREG SAWYER RP is from Facility Anonymous

Organization: CCCFPD

Primary Phone Number: 925-933-1313 Secondary Phone Number: _____

Email: _____

Address: _____

City: _____ State: _____ Zip Code: _____

FACILITY / LOCATION OF INCIDENT:

Name: EBMUD PIPELINE PROPERTY CUPA Facility I.D.: _____

Phone Number: _____

Address: 1221 FRANQUETTE AVENUE Unit: _____

City: CONCORD State: CA Zip Code: 94520

Location Description: HWY 242 WEST BOUND AND FRANQUETTE AVENUE

INITIAL INCIDENT DESCRIPTION: RELEASE OF DIESEL FUEL AND OIL FROM TRACTOR TRAILER ACCIDENT

INCIDENT TYPE / DESCRIPTION:

Community Warning System Level (Circle Highest Level): N/A 0 1 2 3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion	<input type="checkbox"/> Fatality (one or more)	<input type="checkbox"/> Tank Truck	<input type="checkbox"/> Storm Drain/Creek
<input type="checkbox"/> Spill or Release	<input type="checkbox"/> > 24 hrs. Hospital, 3 or more people	<input type="checkbox"/> Railroad	<input type="checkbox"/> Drug Lab
<input type="checkbox"/> Startup or Shutdown	<input type="checkbox"/> Flammable Vapor Cloud	<input type="checkbox"/> On Water	<input type="checkbox"/> Disposal/Abandonment
<input type="checkbox"/> Flaring	<input type="checkbox"/> > 5,000 lbs.	<input type="checkbox"/> Pipeline	<input type="checkbox"/> Odor Complaint
<input type="checkbox"/> Upset		<input checked="" type="checkbox"/> Fuel Tank	<input type="checkbox"/> Other:

Time Enroute to Scene: 1050 HRS Time Arrived On Scene: 1130 HRS Time Departed From Scene: 1419 HRS

REFERRED TO OTHER AGENCY: N/A

DTSC STATE FUNDING (if applicable): CLU/ERER Number: N/A

STORMWATER STATUS (if applicable): Actual Discharge Potential Discharge



AGENCIES ON SCENE OR NOTIFIED:

Agency Type	Agency	O/N	Contact Person	Phone Number	Case Number
Fire Department	CCCFPD	O	CAPT. GREG SAWYER	925-933-1313	
Law Enforcement	CHP	O	T. PUCKETT / C. FLORES	925-646-4980	LOG 865
Air District					
State OES					
	CALTRANS	O	CANN JOHNSON	408-859-8793	
	EBMUD	O	RALPH ENDRISS	209-649-8035	
	EBMUD	N	DREW LERER	510-292-9004	

REPORT:

ON 2/18/2017 AT APPROXIMATELY 1038 HRS CONTRA COSTA HEALTH SERVICES - HAZARDOUS MATERIALS PROGRAMS (CCHS-HMP) WAS CONTACTED BY CONTRA COSTA COUNTY FIRE PROTECTION DISTRICT (CCCFPD) REGARDING A 20-25 GALLON DIESEL FUEL RELEASE FROM A TRACTOR TRAILER ACCIDENT.

AT APPROXIMATELY 1040 HRS CCHS-HMP HAZARDOUS MATERIALS SPECIALISTS (HMS) TOUGERON, HAGEN, HICKMAN, FRIEDMAN, VAZQUEZ RESPONDED TO THE SCENE.

AT APPROXIMATELY 1130 HRS HM3 AND HM4 ARRIVED AT THE SCENE. HMS TOUGERON SPOKE TO CCCFPD CAPTAIN SAWYER ENGINE 6. CAPTAIN SAWYER STATED THAT AT APPROXIMATELY 0741 HRS A TRACTOR TRAILER DROVE OFF WEST BOUND HIGHWAY 242 AND CRASHED CAUSING A RELEASE OF DIESEL FUEL TO THE GROUND. CAPTAIN SAWYER STATED THAT THE PASSENGER SIDE FUEL TANK WAS REMOVED FROM THE TRUCK DURING THE CRASH. THE DRIVER WAS TRANSPORTED TO A LOCAL HOSPITAL.

AT APPROXIMATELY 1145 CCHS-HMP IDENTIFIED THE SPILLED MATERIAL TO BE A COMBINATION OF DIESEL FUEL AND MOTOR OIL. SEE ATTACHED PHOTOGRAPHS.

AT APPROXIMATELY 1210 HRS CCHS-HMP MADE FIRST ENTRY TO CLEAN UP THE SPILLED FUEL/OIL

AT APPROXIMATELY 1240 HRS CCHS-HMP MADE SECOND ENTRY TO CLEAN UP THE SPILLED FUEL/OIL AND SOIL

AT APPROXIMATELY 1300 HRS CCHS-HMP REMOVED APPROXIMATELY 5 GALLONS OF FUEL FROM THE REMOVED DIESEL FUEL TANK.

CCHS-HMP CONTAINERIZED APPROXIMATELY 45 GALLONS OF DIESEL FUEL / OIL LIQUID INTO A 55 GALLON METAL DRUM AND APPROXIMATELY 40 GALLONS OF CONTAMINATED SOIL, DEBRIS, ABSORBENT PADS, AND PPE SOLIDS INTO A 55 GALLON METAL DRUM. CCHS-HMP TRANSPORTED THE WASTE MATERIAL UNDER A BILL OF LADING TO CCHS-HMP STORAGE YARD FOR PROPER DISPOSAL.

AT APPROXIMATELY 1330 HRS CCHS-HP PLACED 4 LENGTHS OF 10 FOOT SOFT BOOM ACROSS A WATER DRAINAGE PATHWAY TO PREVENT ANY RESIDUAL FUEL FROM REACHING A STORMDRAIN.

AT APPROXIMATELY 1400 HRS CCHS-HMP SPOKE TO MR. DREW LERER, EBMUD, REGULATORY COMPLIANCE. MR. LERER STATED THAT HE WIL BE CONTACTING A CLEANUP CONTRACTOR TO REMEDIATE THE CONTAMINATED SOILS.

CCHS-HMP CLEARED THE SCENE AT 1419 HRS

CENTRAL CAL TRUCKING
3032 E. CENTRAL AVENUE
FRESNO, CA 93725

TRUCK DRIVER MICHAEL RYAN
COMPANY MECHANIC DANIEL LABROVICH 408-550-5616
OWNER PHIL CHRISTMAN 559-706-7078

Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan

Report Prepared by: C. TOUGERON