

ANNA M. ROTH, RN, MS, MPH
 HEALTH SERVICES DIRECTOR
 RANDALL L. SAWYER
 DEPUTY HEALTH DIRECTOR
 MATTHEW S. KAUFMANN
 ACTING DIRECTOR OF HAZARDOUS MATERIALS PROGRAMS



CONTRA COSTA
 HAZARDOUS
 MATERIALS PROGRAMS

4585 Pacheco Boulevard, Suite 100
 Martinez, California 94553
 Ph (925) 655-3200
 Fax (925) 646-2073
 ccchazmat@cchealth.org
 www.cchealth.org/hazmat/

COMPLAINT, INCIDENT, AND NOTIFICATION REPORT FORM

Type (Circle One): C I N

CASE NUMBER: 210716 --01

Received Date: 07/16/21 Received Time: ~1000 Received By: DV Lead: DV
 Incident Date: 7/16/2021 Incident Time: ~1000 Assigned to: Assigned Date:

COMPLAINANT / REPORTING PARTY:
 Name: Sam Ryerson RP is from Facility Anonymous
 Organization: SFIC Cal OES # (if applicable)
 Primary Phone Number: 925-689-2414 Secondary Phone Number:
 Email:
 Address: 4040 Pike Lane
 City: Concord State: CA Zip Code: 94520

FACILITY / LOCATION OF INCIDENT:
 Name: SFIC Corporation CUPA Facility I.D.: 773576
 Phone Number:
 Address: 4040 PIKE LN CONCORD, CA 94520 Unit:
 City: State: Zip Code:
 Location Description:

INITIAL INCIDENT DESCRIPTION:
 Surfactant spilled and entered the storm drain

INCIDENT TYPE / DESCRIPTION: 0 1 2 3
 Community Warning System Level (Circle Highest Level): N/A 0 1 2 3

FACILITY	ISO / MCAR	TRANSPORTATION	MISCELLANEOUS
<input type="checkbox"/> Fire or Explosion <input type="checkbox"/> Spill or Release <input type="checkbox"/> Startup or Shutdown <input type="checkbox"/> Flaring <input type="checkbox"/> Upset	<input type="checkbox"/> Fatality (one or more) <input type="checkbox"/> > 24 hrs. Hospital, 3 or more people <input type="checkbox"/> Flammable Vapor Cloud > 5,000 lbs.	<input type="checkbox"/> Tank Truck <input type="checkbox"/> Railroad <input type="checkbox"/> On Water <input type="checkbox"/> Pipeline <input type="checkbox"/> Fuel Tank	<input type="checkbox"/> Storm Drain/Creek <input type="checkbox"/> Drug Lab <input type="checkbox"/> Disposal/Abandonment <input type="checkbox"/> Odor Complaint <input type="checkbox"/> Other:

Time Enroute to Scene: Time Arrived On Scene: Time Departed From Scene:

REFERRED TO OTHER AGENCY:



DTSC STATE FUNDING (if applicable): CLU/ERER Number:	STORMWATER STATUS (if applicable): <input type="checkbox"/> Actual Discharge <input type="checkbox"/> Potential Discharge
--	---

AGENCIES ON SCENE OR NOTIFIED:

<u>Agency Type</u>	<u>Agency</u>	<u>O/N</u>	<u>Contact Person</u>	<u>Phone Number</u>	<u>Case Number</u>
Fire Department		O			
Law Enforcement		N			
Air District					
State OES		N			
City Concord Public Works		O			

REPORT:

7/16/2021:
 At approx 10:00AM the SFIC Corp facility manager Sam Ryerson contacted CCHS - HMP to report a spill that entered the storm drain, CCHS Inspector notified CCC-FPD. CCHS-HMP & CCC-FPD were dispatched to the scene.

CCHS HMP dispatched HM1 (Box Truck) DV + IW. KA arrived later in her personnel vehicle.

Upon arrival CCHS-HMP met to discuss the incident with CCC-FPD Captain Chris Hummel and SFIC facility manager Sam Ryerson.

CCHS-HMP Initial Assessment: Between 70 - 120 gallons of TEA Laury Sulfate (a base material of shampoo and cosmetic) had entered the storm drain.

CCHS-HMP Hazmat Objectives / Operations: CCHS initial objectives were to identify the storm drains, the direction the spilled materials flowed and clean out the storm drains.

CCHS notified City of Concord Public Works
 CCHS notified CalOES

Clean up Operations
 City of Concord Public Works Identified the storm drain path using their GIS, then flushed and vacuumed the spilled material inside the storm drain with their vacuum truck.

Post Clean up:
 After reviewing the SDS the spilled materials was determined to be non-hazardous and the vacuum truck waste was disposed of at City Concord Corp Yard on Gasoline Alley.
 CCHS inspector discussed spill prevention BMPs with the facility and requested they purchase a storm drain cover to use during chemical loading / unloading operations.

Additional Required Items: Bill of Lading, Request for Invoice, and Site Safety Plan

Report Prepared by: DV